





Calibrate, set reference in TopSpin



Expand to display reference peak.




Set Reference button

Move vertical red line centered at top of reference peak

Click Mouse-1

Enter Calibration value



calibrate

Spectrum calibration frequency

Cursor frequency in ppm: 0

OK Cancel